

GOLD MEDALS



VIENNA 1903
WIESBADEN 1905

Franz Swaty

GOLD MEDALS



COLOGNE 1903
BARCELONA 1927

INVENTOR & MANUFACTURER OF THE
GENUINE FRANZ SWATY HONES

STANDARD OF THE WORLD

These Hones have a world wide reputation for the past 60 years.

Made on scientific principles of the finest abrasives and each and every one is fully and unconditionally guaranteed.

Over 5 MILLION in use.

UNEQUALLED IN QUALITY

Carried in stock by all leading Cutlery and Barber Supply Dealers.

BEWARE OF IMITATIONS

FRANZ SWATY RAZOR HONES

Registered Trade Mark



DIRECTIONS FOR USE

Hone your razor exactly opposite from stropping that is, draw **AGAINST** the edge instead of **AWAY**.

Lay the razor flat on the hone (do not raise the back of the blade). Draw the blade from right to left **AGAINST** the edge as figure A.

Turn razor on back, and draw from left to right (against the edge) as in figure B.

HONE LIGHTLY. Very little pressure is needed. The edge of a razor is extremely thin and sensitive, and heavy pressure will take off instead of putting on the edge. Number of strokes necessary to put a keen cutting edge depends on the condition of your razor. Ordinarily six to ten strokes is sufficient. Great care should be taken not to over-hone a razor, as it produces a fine wiry edge which will curl over when coming in contact with the beard.

Use fine oil, water or **SWATYOL**.

To clean hone use emery paper dry or pumice stone with water.